

390374

User manual (Eng)



It is recommended to read this user manual carefully and keep it for future reference.

Weather station with humidity and temperature measure function.

Temperature: -10-50°C - Accuracy +/- 1°C

Humidity: 20-95% - Accuracy 1%

Works with a AG10/LR1130 battery, remove the battery stopper before the first use.



This symbol both in the product and its user manual indicates that at the end of the device's electrical life, it should be recycled separately from your household waste. There are adequate means to dispose of this material for proper recycling. For more information, contact your local authorities.